

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

28th October, 1908.

Dear Sirs,

With reference to the classification in the Society's Register Book of your steamer "SINGU", I am directed to acquaint you that the Committee have had before them at their meeting yesterday a report received from the Society's Surveyor at Bombay of survey held on this vessel afloat on account of a leak on the starboard side of No.2 tank.

The Surveyor reports that a hole was found in one plate on the starboard side close to the keel plate, and that temporary repairs have been effected. He recommends, however, that the necessary permanent repairs be carried out at the first convenient opportunity, and in the circumstances I shall be obliged if you will kindly let me know when and at what port it will best suit your convenience to comply with this recommendation.

I am, Dear Sirs,

Yours faithfully,

Messrs. The Burmah Oil Co. Ltd.,

175, West George Street,

Secretary

Lloyd's Register
Foundation
W1206 - 0157