

Received by Chief Ship Surveyor 24/10/08. Received from Chief Ship Surveyor _____
 VESSEL'S NAME Red Singh Rpt. Bomb No. 362

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Leakage

The Bombay Surveyor reports that he has examined this vessel afloat owing to a leak on the starboard side of No.2 tank, and he found a hole in one plate on the starboard side close to the keel plate. Temporary repairs have been effected and he recommends that permanent repairs should be carried out at the first convenient opportunity.

It is submitted the Owners be informed and asked to state when and at what port it will be convenient for permanent repairs to be effected, action in the meantime being deferred.

A copy of the Bombay Surveyors report should be forwarded to the Calcutta Surveyor and he should be requested to offer any remarks he may wish to make thereon for the information of the Committee.



© 2020

Lloyd's Register
Foundation

W1206-0158

RBW
C.R.J. 26/10/08