

Cordoba
ex Taurus

Chief Surveyors _____

Received from Chief Surveyors _____

S NAME Steel S.S. "GALTYMORE". Report Grk. No 17459

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey _____

When due _____

Downton pump dispensed with for the present. See Owners' letter attached.

100 A.1.

2 Dks. (Steel).

Cell DB 331' 958t. FPT 122t. APT 19t.

EK. 7 BH. Cem. Lloyd's A. & C.P. P49', B113', F38'.

23. 5. 19.

Lloyd's Register
Foundation