

13 JUN 1932

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME Steel Sc. "KIFUNEZAN MARU" No 2 Report Lon. No. 97603a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

ure of Survey _____ When due _____

The class is subject to the solepiece of sternframe, repaired by electric welding 2.29, 1.30 & 2.32, being specially examined at the next dry docking.

The following cable has been received from the Kobe Surveyors :-

"'YUGAO MARU' 'KIFUNEZAN MARU' 2 SOLD TO CHOSEN YUSEN. OWNERS DO NOT
"WISH CLASS RETAINED. LETTER FOLLOWS."

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...



© 2021

Lloyd's Register
Foundation

W1208-0227