

"ELENI II"

It is submitted the Surveyor be advised that a full Special Survey (D) for reclassification should be held and all necessary repairs effected. The shell plating should be drilled and gauged and results forwarded for consideration.

The necessary particulars of scantlings from the First Entry Reports and plans should be forwarded for the Surveyor's guidance.

*In Mr. Kerris to  
arrived Sir:-*

*R.S.  
25/2/48*



© 2021

*Reck*  
Lloyd's Register  
Foundation  
25th February, 1948.

W1208-0242