

BS due 4.32 partly held.
To be completed at first opportunity.
Screw shaft examined.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that this vessel WILL BE eligible for the record, BS. 3.32 when the safety valves have been adjusted.

S(CL) 3.32.

L.L.
18/4/71.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation