

15c, 1, 14.

1

Sent to Chief Surveyors

23. 4. 14

Received from Chief Surveyors

VESSEL'S NAME

M. S. S. Saint Quentin Report

No.

16642

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry

When due

÷ 100 A. 1. (Steel) "Shelter dk with pebb"  
 2 Lths (Stl) + Shelter dk (Stl) web frames, longitudinal framing  
 W. B. Cell DBa 126' 4" E+B 36' F 184' 1103t. D of 30' 824t  
 Fk. 617H. Cmn "Layers a & b" FRT 18t. APJ 29t

M. W. 10. 14. 14  
 24. 4. 14



© 2020

Lloyd's Register  
Foundation

W1212-0144

BEAMS, Second, Third & Fourth Deck, Single  
 Angle, Bulb Angle, Plate, Tee Bulb or Channel  
 Angles on upper edge

Deck, Material and thickness