

If the vessel has water tanks examined. Also state the amount of deterioration on the side of the inner bottom plating, especially in the boiler space.

For fishing purposes 2-27

Report, No. 449 2 Port Mil.

# POSTPONED SURVEYS.

assigned as now verified

Case of the Steel Sc. K. "MURIELLE"

08900 in Reg. Bk. 107/19 tons, Built 1919-6

Classed +100 A1 +LMC Owners E. J. Hellings  
For fishing purposes 6.27  
S.S. No 2-27 BS 3.31 CL 8.30  
Port of Registry Milford

Survey Due Special Survey No.3 due 6,31.

The Milford Haven Surveyor writes:-

"The Owner, Mr. Hellings, made a verbal request to me for the survey in question to be deferred for a few months as the vessels have been doing so badly, and I think the request merits the favourable consideration of the Society's Committee".

"The vessels owned by Mr. Hellings are well found and kept in good condition".

Committee's Minute

FRI. 10 JUL 1931

Approved

*Whitaker for approval*  
*[Signature]*

9.7.31



© 2021

Lloyd's Register Foundation

or I.M. of ste if on Ev in put on, M

Tards, &c.

in, how asc

le if wed

nt letter

No. of

State if n

ngth

(on ton

ule lengt

& Warp

g and Ru

Regis

is class