

... of the inner bottom plating, especially in the boiler space.
Report, No. 449 2 Port Md.

100 A1 10, s
For Fishing pu
0.0 m. 1 No 2

Lloyd's Register of Shipping,

Milford Haven, July 6th 1931.

LLOYD'S REGISTER
RECEIVED
-7 JUL 1931
Ann.
LONDON

Steam Trawler "MURIELLE"

Dear Sir,

Reverting to your letter of the 29th ultimo respecting the Special Survey No.3. The owner Mr. Hellings made a verbal request to me for the survey in question to be deferred for a few months as the vessels have been doing so badly, and I think the request merits the favorable consideration of the Society's Committee.

The vessels owned by Mr. Hellings are well found and kept in good condition.

I am Dear Sir,

Yours faithfully,

John Stocks.

The Secretary, H,
London.



© 2021

Lloyd's Register
Foundation
W12 13-0206

rd (if as
and no
om ?

tems --

Copper,
(Stee
Whe

Boats ...

Masts, 1

Conditio

(Stat

Sails...

Equipm

Anchors

Cables

„ Is

„ B

Hawser

Standin

el in th
remain

Referred to Mr. S. A. Hill.

msd

-7 JUL 1931

No. 3 due 6 31



© 2021

Lloyd's Register
Foundation

Faint, mirrored text from the reverse side of the paper, including the words 'LLOYD'S REGISTER' and 'FOUNDATION'.