


14 JUN 1933

Steam Trawler "BASSANIO"

This case is fully stated in endorsement dated 8.6.33, when the Hull Surveyors were communicated with regarding the Committee's decision to expunge this vessel's class from the Register Book with a Black Line, and it was pointed out to them that the Owners' statement that repairs were executed when the vessel was placed in dry dock on the 25th ultimo was not borne out by their report, which definitely stated that the vessel had sailed without the repairs having been put in hand, and that the Committee's action was taken on this understanding. Mr. Mackirdy, ^{Principal} ~~the Senior~~ Surveyor at Hull, was requested to investigate the circumstances closely and report thereon for the Committee's further information in the matter.

A letter has now been received from Mr. Mackirdy setting forth in full detail the circumstances of the case, from which it is seen that the repairs recommended by the Society's Surveyors were not put in hand before the vessel sailed. Mr. Mackirdy's explanation appears to be satisfactory, and it is submitted the Owners might be advised of the contents of his letter.



13.6.33




© 2020

Lloyd's Register
Foundation

W1217-0123