

WB=CellDBorDBa

feet; uE&B

feet; f

feet

Destined Voyage

Particulars of Classification precisely as in B...

Chief Ship Surveyor

Received from Chief Ship Surveyor

21 OCT 1931

NAME Steel Sc. "AGHIOS SPYRIDON"

Rpt.

Msl.

No. 7720

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Survey

The class is subject to indented plating port side and bottom plating etc. being dealt with at the first opportunity and permanent repairs being carried out to damaged shell plating etc. at the Owners' convenience.

The Marseilles Surveyors now report the vessel placed in dry dock, bottom coated and repairs effected to tank margin plating and connections on the port side of No.2 hold.

The indented plating has not been dealt with.

An examination has been made of the weather decks, hatchways, casings, ventilators, boats, general equipment, masts, rigging, windlass, steering gear, forward holds above ceiling and machinery space above platforms.

The Surveyors were informed by the Owners' Representative that the vessel would be docked again shortly for the renewal of the propeller and the Owners propose to carry out the 3rd S.S. No.1, due 10.31, some time within the year of grace and this proposal, in the Surveyors' opinion, merits favourable consideration.

It is submitted the vessel appears worthy to remain as classed with record of survey 10.31, subject as above.

100 A.1. Spar deck Subject etc. 10.31/31

W1217-0185



© 2020

Lloyd's Register Foundation

Convenience.

Survey Fee (per Section 29)

Rs. 650.-

Fees applied for

12.10.31