



Sunderland
May 10 1901

Messrs

Lloyds Surveyors

Johns

Ssgl

Dear Sir

With reference to the
after hood over the steering
gear you added to our
profile plan of the above
vessel, we beg to state
that this vessel was
contracted for prior

Sec 36 of the new rules
came into force and we
are therefore exempt from
fitting this hood

Yours truly
The John Priestman & Co.
W. H. Syles



© 2020

Lloyd's Register
Foundation

as requested in your letter of 18th inst

Thickness of furnace plates

21/32 Description

W1217-0195

Length

Dia. of

own plates

6 1/2

joined or

of riveting

plates

key boiler

ves

If fitted

hydraulic P

le

roller

ma

per rule

13

3

Electric Light

t belongin

12

12

12

12

12

12

12

12

12

12

12

12

12

12

12

12

12

12