



Lloyd's Register of Shipping.

2-6-30
2-29

2500,12,17.

101 Tower Building

ned) as
verified

15 FEB 1933

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S.K. "CHIEFTAIN" Report Lon. No. 984008

For the CHIEF SHIP SURVEYOR and CHIEF-ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24.5.32.)

Nature of Survey _____ When due _____

The 2nd S.S. No.3 became due 6.32.

In reply to enquiry, the Secretary to the Liverpool Committee now forwards a letter from the new Owners' Managers stating it is not their intention to submit the vessel for survey for renewal of class.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...

M. of Wood
on Felt).
on, Month.

, &c.

w ascertain

wedges re

etter

of

if now ran

board)

ength

owner & Warps

anding and Running Bi



W1218-0026

Lloyd's Register
Foundation

Handwritten signatures and dates: 15/2/33