

Surveyors.

Received from Chief Surveyors

AME Steel Sc. "DESIO"

Report Lon

No. 98456A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee: "the endorsement to contain a succinct summary of any repair that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

When due

The class is subject to indented keel plates aft being dealt with at the Owners' convenience and permanent repairs to indented shell plates &c. abreast No.4 hatch port side at first convenient opportunity and the rudder being specially examined at the next dry docking.

The 2nd S.S. No.2 will become due 4,34 (after an early No.3).

On the 3rd instant the Naples Surveyor forwarded a letter from the Owners reading as follows:-

"We regret to inform you that our Directing Committee have decided to withdraw the class of the ss. "CAMOGLI", "DESIO" & "GAETA" from Lloyd's Register."

"The decision in question is necessary merely to keep uniformity of administration with the other vessels of this Company".

The Surveyor stated that he had interviewed the Owners with view to the question of the withdrawal of this vessel's class being -considered and no action was taken pending the receipt of a further communication from him.

The same Surveyor now forwards a further letter from the Owners reading as follows:-

"-----we have examined your good arguments but we regret having to inform you that on account of the reasons stated in our letter of the 2nd ultimo we cannot reconsider our previous decisions regarding the class of the steamers "CAMOGLI" "DESIO" & "GAETA" with your Society".

W1223-0133 1/2


© 2020
Lloyd's Register
Foundation

S.S. "DESIO" (2)

It is submitted the class of this vessel be withdrawn
from the Register Book and three dots (...) inserted in lieu,
indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...

[Signature] *[Signature]*
17.3.33



© 2020

Lloyd's Register
Foundation

W1223 - 0133 2/2