

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

25th March, 1912.

Gentlemen,

E. With reference to your First Entry Machinery Report No. 61988 in the case of the S.S. "BIRMA" I have to request that you will let me know by telegram in the morning whether you are correct in stating that the diameter of the propeller is 18 feet, as this with no liners on the screw shaft would require the screw shaft to be 15.39" diameter by the Rules instead of 15" as stated on the report.

I am, Gentlemen,

Your obedient Servant,

Secretary.

The Surveyors,

NEWCASTLE-ON-TYNE.



© 2021

Lloyd's Register

W1275-0175  
Foundation