

Awing Dk.
Total under U
Do. of Poop
Do. of Bridge
Do. of Forecastle
Do. of Houses on
Do. of excess of

F.E.

Received by Chief Ship Surveyor 6. 12. 07

Received from Chief Ship Surveyor

VESSEL'S NAME Sa. S. S. "Bintang" Report Cpu No. 2573

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .		
Spar Sheerstrake . .		
Description of Framing:— <u>Deep (Bulb angle) framing.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\pm 100 A 1$ ("Steel") "Awing deck" with freeboard," as recommended. The Summer freeboard of 7' 3" from centre of disc to top of statutory deck line at awing deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

$\pm 100 A 1$ ("Steel") "Awing deck with freeboard."
1 DR (Stl) & deep framing & Awing Dr. (Stl)
N. B = Cell DB a 96' u E 18' f 138' 535t FPT 30t APT 15t
FK 5BH Cum. Lloyd's A & C RFD 33'

500-5-03.

W/227-0178

C. H. J.
2019
6/12/07

Lloyd's Register
Foundation

WEB-FR

N