

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report No 74 Port Trunk

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.  
4A- Barge 3,2  
For River ser

5m,7,20.

## POSTPONED SURVEYS.

Case of the Steel Barge "NAVEGADORA NO. 75"

No. 02642 in Reg. Bk. 434 - 436 tons, Built 1914-5 mo

Classed + A - Owners Gotham Marine Corporation

For River service  
3.26

Port of Registry New York

ss no 2.26 Carrying petroleum - bulk

Survey Due Special Survey No. 3 due 3. 30

The usual preliminary Notice was sent to the Owners in regard to the above survey on the 7th April, 1930 to which no reply has been received, and the Chief Surveyor United States and Canada states that several enquiries addressed to the Owners in regard to the matter have failed to elicit a reply; also that, in his opinion, the Owners are not interested in maintaining the vessel's class.

Submitted for the consideration  
of the Committee.

FRI. 13 JUN 1930

Committee's Minute

Decision

Deferred

P.M.A.

12.6.30



© 2020

Lloyd's Register  
Foundation

Copper, or  
(State  
When p  
Boats  
Masts, Yards  
Condition, h  
(State t  
Sails  
Equipment  
Anchors, No.  
Cables (Stat  
length  
(on  
Rule le  
Hawser & W  
Standing and

vessel in the Reg  
to remain as cla