

of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 24 Port Trip

CHARACTER
* for Special
Date of last Sur-
Periodical S
A- Barge
For River

COPY.

Lloyd's Register of Shipping,
NEW YORK.

2nd June, 1930

Dear Sir,

Barges "NAVEGADORA No.75"
"NAVEGADORA No.76"
"NAVEGADORA No.77"

With reference to your letters of the 7th April last addressed to the Owners regarding the Special Survey No.3 of the above named vessels, I may say that several inquiries have been addressed to the Owners regarding the proposed arrangements for carrying out this inspection, but so far no reply has been received.

I am of the opinion that the present Owners are not interested in maintaining their class.

I am, Dear Sir,

Yours faithfully,

The Secretary,
LONDON.



© 2020

Lloyd's Register
41233-0154
Foundation

pic
ng
lk
p.No
eeboar
Ship
y who
rom
25t
her Items
Cop
Boa
Mas
Cond
(S
Sails
Equi
Anch
Cable
"
"
Haws
Stand

vessel in th
to remain

transfer in
or below the space

COPIES

Reference to register

W. M. JOHN.

1891, June 30

THE REGISTER
LLOYD'S REGISTER
15, ABchurch Lane, LONDON, E.C. 4

With reference to the ...

... of the ...
... of the ...
... of the ...
... of the ...

I am, Dear Sir,

Yours faithfully,

LONDON

Ms. 2 June 30



Lloyd's Register Foundation

If so, is the Report sent now, or when will it be sent?

Periodic cause on each and be repla the be
In dama offer
REPAIR

SUMMARY

PRESEN
F
R
R

Decks
Ganking
Coaming
Beams &
Outside
Breastho
Transoms
Frames
Reverse
Longitud
Transver
Floors
Keelsons
Stringers
Inner Bot

Gen

at st

Survey F

Transfer Ink
Write on or below the space for Committee's Minute.