

s. s. "PATO REAL".

The screwshaft survey and the modified survey of the
became
oil engines due 8.30.

The Surveyors at Buenos Aires now state they have
received a letter from the Owners' Superintendent stating that
it is not desired to retain this vessel's class with this
Society.

IT IS SUBMITTED that in the circumstances the class of
this vessel might be withdrawn from the Register Book, and three
dots (...) inserted in lieu, indicating withdrawal of class at
Owners' request.

Withdraw class.

Insert ...

[Signature] *[Signature]*
21.11.30.

Items:—

Copper, or
(State
When p
Boats
Masts, Yar
Condition, h
(State i
Sails.....
Equipment
Anchors, No
Cables (Sta
,, length
(or
,, Rule l
Hawser & V
Standing and

sel in the Re
remain as cl



© 2020

W1233-0198

Lloyd's Register
Foundation

Survey Fee (per Section 20) £ :

Special Damage or Repair Fee (if any)..... £ :

Fees applied for,

19.....