



14 NOV 1930

Lloyd's Register of Shipping,

71, Fenchurch Street,

London, 3rd October, 1930

E.C.3.

H.

To the Surveyors at BUENOS AIRES.

essel's Name, Motor Tug "PATO REAL"


Lo 27. 11. 30
28/11/30

QUESTION.	ANSWER.
<p>I shall be glad if you will ascertain and let me know what arrangements have been made for carrying out the Screwshaft survey and the Modified Survey of the Oil Engines which became due last August.</p> <p><i>Sat</i></p>	<p>Date:—</p> <p><i>28th October, 1930.</i></p> <p><i>Tug "Pato Real".</i></p> <p><i>We are in receipt of a letter from the Buenos Superintendent stating that the Cia Argentina de Lanchas do not desire to continue this vessel's class in the Register Book.</i></p> <p><i>G. Williamson.</i></p>

Other Items:—

Copper, (Sta)
Wh
Boats
Masts,
Condition
(Stat
Sails.....
Equipme
Anchors,
Cables (S
" le
" R
Hawser
Standing

the vessel in the
"to remain a



© 2020

W1233-0199

Lloyd's Register
Foundation

Survey Fee (per Section 20)£

Special Damage or Repair Fee (if any).....£
(per Sec. 20)

Fees applied for,

19.....

Received by me.

0001 0001 0001

0001 0001 0001

0001 0001 0001

0001 0001 0001

0001

0001 0001 0001

0001 0001 0001

© 2020

Lloyd's Register
Foundation

REPAIR

In damage
offere

(Periodic
cause
on acc
and be
replace
the ba

Last

of the
grinders,

date

0001 0001 0001

0001 0001 0001

0001

0001 0001 0001

0001 0001 0001

0001 0001 0001

0001 0001 0001

0001 0001 0001

0001

New shaft
Modified survey 7 at
Lyons due 8/20

0001

General

this su
survey

Survey Fee (per

Special Damage

Write on or below the space for Committee's signature.