

PORT -Jacksonville, Fla.-

-Fifth, May 1917-

This is to Certify that
 - HUGH BOYLE -

the undersigned Surveyor to this Society did at the request of
 H. F. Brown, Esq., owner's representative, survey the Twin Screw
 Barge "PEDRITO" of Boston, 336 Tons Gross Register, for the
 purpose of ascertaining the nature and extent of damage stated
 to have been caused by striking some submerged object as vessel
 left the ways on day of launch.

On examination of the vessel while lying in Merrill-
 Stevens Company's Drydock on the Twenty-sixth of April 1917,
 found shell plates B-1 Starboard and shell plates A-6 and A-7
 Starboard to be indented and considerable buckled.

 RECOMMEND: - That the plates indented and buckled be
 faired in place and that rivetting in way of same be over-
 hauled and made good.

Hugh Boyle

(Fee \$35.00)



© 2020

Lloyd's Register
 Foundation

W1237-0136