

Report 31 Dec 1919 When handed in at Local Office 3.1.1920 Port of Glasgow

Survey held at Glasgow Date, First Survey 16.12.1919 Last Survey 30 Dec 1919 on the Wood, Iron or Steel S.S. ONEGA Master R. Logan - 19

Built at Londonderry By whom Nof Ireland S.B.C. Ltd. When Owners W. Thomson + Co. Port belonging to Leith.

Owners' Address (if not already recorded in Appendix to Register Book) d Afloat or in Dry Dock? Yes Name of Dock Prince of Wales Destined Voyage Cardiff for orders.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements) 100A-1 (Class Contemplated)

Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

OR EXAMINATION AS PER RULE, FOR Survey for Classification, [advanced] done :- See London Letter. M. 11 Dec. 1919.

Hawse pipe deck plates fitted, wood deck in way laid, Caulked and payed and deck hose tested and made satisfactory. Machinery basings erected after shipment of machinery, and rings & Bridge deck in way hose tested & made satisfactory. Steam Reversing Engine, quadrant and tiller fitted and tested under steam and found in working order. No opportunity was given to test the auxiliary means of lifting by relieving tackles, but it was stated by the Supt. that this could be tested at Cardiff, to which port the vessel is proceeding. Cardiff Surveyors advised.

DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
and Paired or Repaired								
Repaired in place								
CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder
	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblg. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.
						Scuppers	Cargo Hatchways	Hatches
						Planing of Wood Vessels	Caulking	Planing of Wood Vessels
						Treknails	Breasthooks & Stemson	Transoms, Pointers, & Crutches
						Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shelves
						Salting (State if examined.)		
								Copper, or Y.M. of Wood Vessels (State if on Felt.)
								When put on, Month Year
								Boats
								Masts, Yards, &c.
								Condition, how ascertained (State if wedges removed)
								Sails
								Equipment letter
								Anchors, No. of
								Cables (State if now ranged)
								length size (on board)
								Rule length size
								Hawser & Warps
								Standing & Running Rigging

Observations, Opinion as to Class, Recommendation, &c.:- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

The above is submitted for the information of the Committee.

Section 28 Fees applied for, 19 Received by me, 19

Is Certificate required? If so, to be sent to

