

se.k. "VENATOR".

---

15 OCT 1931



The Boiler Survey became due in 5,31 and the screwshaft survey in 8,31.

The Grimsby Surveyors now forward a letter from the Owners requesting that the vessel be withdrawn from the Society's classification.

IT IS SUBMITTED that the vessel's class be withdrawn from the Register Book, and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

  
14.10.31.  




© 2020

Lloyd's Register  
Foundation

W1238-0074