

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... When handed in at Local Office... Port of... London

No. in Reg. Book... Survey held at... Date, First Survey... Last Survey... 19

53507 on the Wood, Iron or Steel "T, 18"

TONNAGE:— Built at Haverton Hill on Tees By whom Furness S.B. Co. Ltd. When 1926

GROSS 225 Owners Tropical Oil Co. Owners' Address

UNDER DK 225 Managers International Petroleum Co. Ltd. Port belonging to (British)

NET 225

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 12736 Port Mal

CHARACTER. For Special Survey. Date of last Survey and of Periodical Surveys.

+ A -

For Service on the River Magdalena

Carrying Petroleum in Bulk

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

AIRS, OR EXAMINATION AS PER RULE, FOR