

California

12.1.17

Shuss

Lumleaf

Received from Chief Surveyors

Report

Sl

No. 36579

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

When due

* 100 A.1. (Steel) Carrying petroleum in bulk.

2 Dk (Steel) & Web frames.

Cell DB ~ E+B 70' 3086 . D.T. + 27' 2916 . F.P.T. 124 C. A.P.T. 706

FK. 22 BH (21 BH to upper Dk 1. BH to 2" Dk) pl. cen.

Logs axed. P44' B161 F42'

M
12.1.17



© 2020

Lloyd's Register
Foundation

W1241-0130