

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 26th June 1913 When handed in at Local Office JUN 27 1913 Port of Newcastle-on-TyneNo. in Survey held at Wallsend Date, First Survey and Last Survey 23rd Jun 1913
Reg. Book. Sup. " (No. of Visits)75 on the Wood, Iron or Steel SS Novgorod Master

TONNAGE:—

GROSS Built at Sunderland By whom Sir J. Laing & Sons When
UNDER DK. Owners Russian Volunteer Fleet Associaⁿ Port belonging to Odessa.
NET Owners' Address ✓
(If not already recorded in Appendix to Register Book).Surveyed ✓ in Dry Dock? Yes Name of Dock Swan & Hunter Destined VoyageWB=Cell DBor DBa feet; uE&B feet; f feet; f
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the timer bottom plating, especially in the boiler space.

Last Report, No. Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.
Years
Assigned
and
expired.
Machinery and Boiler
Surveys
(including date of N.B., if any).* 100A1
(Contemplated)
7.13Society's Freeboard (if assigned) as
painted on Ship and now verified ft. ins.In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

REPAIRS, OR EXAMINATION AS PER RULE, FOR

PaintingNow done:— Vessel placed in dry dock, bottom examined after being cleaned & then coated. Bottom & rudder in good order.

SUMMARY OF DAMAGE REPAIRS:—

Renewed Plates. Frames. R. Frames. Floors. Beams. Str. Plates. Dk. Plates. Other Items:—
Removed and Fair'd or Repaired RENOVED
Fair'd or Repaired in place RENOVED

PRESENT CONDITION OF THE

Good	Stringers <u>Good</u>	Dblg. Plates under Sounding Pipes <u>✓</u>	Copper, or Y.M. of Wood Vessels. <u>Good</u>
Good	Inner Bottom Plating <u>✓</u>	Engine Room Skylights <u>Good</u>	(State if on left.)
Good	State if Tanks have been examined inside <u>✓</u>	Coal Bunkers, Open'gs, Lids, &c. <u>✓</u>	When put on, Month <u>Good</u> Year
Good	State if Tanks now tested. <u>✓</u>	Scuppers <u>✓</u>	Boats <u>Good</u>
Good	Bulkheads <u>Good</u>	Cargo Hatchways <u>✓</u>	Masts, Yards, &c. <u>Good</u>
Good	Ceiling <u>✓</u>	Hatches <u>✓</u>	Condition, how ascertained <u>from d. b.</u>
Good	Cement or Asphalt <u>✓</u>	Planking of Wood Vessels <u>✓</u>	(State if wedges removed) <u>✓</u>
Good	Rudder <u>✓</u>	Caulking ditto <u>✓</u>	Sails <u>Reported good</u>
Good	Steering gear and its connections <u>✓</u>	Treenails ditto <u>✓</u>	Equipment letter <u>✓</u>
Good	Windlass <u>✓</u>	Breasthooks & Stems ditto <u>✓</u>	Anchors, No. of <u>303, 15, 1K</u>
Good	Have Pumps now been examined and found efficient? <u>✓</u>	Transoms, Pointers, & Crutches ditto <u>✓</u>	Cables (State if now ranged) <u>✓</u>
Good	Have Sluice Valves now been examined and found efficient? <u>✓</u>	Timbers of Frame at openings ditto <u>✓</u>	" length <u>Staked to</u>
Good	Have Watertight Doors now been examined and found efficient? <u>✓</u>	Ditto ditto at other places ditto <u>✓</u>	" Rule length <u>be complete</u>
Good		Stringers, Clamps & Shells ditto <u>✓</u>	Hawser & Warps <u>Good</u>
Good		Sarking ditto <u>✓</u>	Standing & Running Rigging <u>Good</u>
Good		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,10," or "to remain as classed and to have record of survey, 1,10 and the notations of ss No. 1-10 and ptND10, &c."

This vessel is now in good & efficient condition & is eligible in my opinion to be classed * 100A1 & to have record of survey 6-13.

ay Fee (per section 22) <u>£</u>	Fees applied for,
ial Damage or Repair Fee (if any) <u>£</u>	<u>19</u>
elling Expenses (if chargeable) <u>£</u>	Received by me,
id Surveyor's Fee (if any) <u>£</u>	<u>19</u>

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character Assigned as above {see minute on T.B. report.

© 2020

Lloyd's Register
Foundation

W1243-0196