

S.S. "SCOTSCRAIG"


The 2nd S.S.No.1 became due 2,32 and no part of
his survey has been held.


Permanent repairs are required to the tank top under
boilers and the engine room tank to be scaled and cement washed
and the main boilers cleaned.

The vessel is laid up at Dundee, and the usual
undertaking has been furnished.

A letter has been received from the United Shipping
. requesting permission for the vessel to be allowed to be
transferred, under tow, from Dundee either to the Forth or
the Tyne, to be laid up again.

It is submitted that provided the Surveyors satisfy
themselves that the vessel is in fit condition to proceed in
tow to the Forth or the Tyne, special attention being paid to
the windlass and steering gear, the Owners' request might be
granted.


2.9.33





© 2020

Lloyd's Register
Foundation