

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓

"ELIE CHENEVIÈRE."

Aug. 12044

The Engines & Boilers removed from an old vessel of the same name have now been fitted in this newly constructed trawler.

It is submitted that this vessel is eligible for

THE RECORD + L.M.C. 9.30 C.L.

53 N.H.P. T 30y 11½ - 18½ - 30 - 22 (S)

I.S.B. 2 1/2 G.S. 30 H.S. 1057.

+ NE EB 98 refitted 9.30 + NB 12 refitted 9.30.

(B)

17/10/30



Lloyd's Register
Foundation

accordance with the rules & duly listed.

2nd cylinders, pistons, slide valves, steam chests, crank & ...