

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Dia. of Tunnel shaft as fitted 9 7/8 Dia. of Crank shaft journals as fitted 9 7/8 Dia. of Crank pin 7 1/8 Size of Crank webs 62 1/2  
collars 9 7/8 Dia. of screw 11-0 Pitch of Screw 14-6 No. of Blades 4 State whether moreable no Total surface work yes

TELEPHONE : GREENOCK 295.



# Lloyd's Register of Shipping,

14, Cross-shore Street,

Greenock, 1<sup>st</sup> August 1927

Reference

Dear Mr. Carey

With reference to your letter of the 29<sup>th</sup> July regarding the Steamer "Hsin Yangtze"; I have to state in reply that there are only two boilers installed in the vessel & that spare coupling bolts were supplied.

Yours faithfully  
H. L. Fletcher

For Mr. Summuck

Noted on JLT  
JLT  
8/8/27



© 2020

Lloyd's Register Foundation

W1244-0215

ERHEATER.

Type

✓

Date of Approval of Plan

✓

Tested by Hydraulic Press