

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 33670 Survey held at Wood, Iron or Steel Sc. Satsuma Manu Date, First Survey Last Survey 19

TONNAGE: GROSS 3089, UNDER DK 2834, NET 1828. Built at Newcastle By whom Tyne I.S.B. Co. LD. When 1918 8

Owners Utsunomiya Kaisoten KK. Owners' Address (if not already recorded in Appendix to Register Book). Port belonging to Takasago.

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. } CHARACTER: for Special Survey, Date of last Survey and of Periodical Surveys.

Last Report, No. 6770 Port Kob. } Machinery and Boiler Surveys (including date of N.B., if any).

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR


SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE			
Decks	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Feet). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	Boats
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Breasthooks	Rudder	Hatches	Equipment letter
Transoms	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Frames	Windlass	Caulking ditto	Cables (State if now ranged)
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	length size (on board)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Keelsons		Ditto ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:— State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and PLND24, &c."

Survey Fee (per Section 29)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W1250-0166

Committee's Minute  
Character Assigned

DISCLOSED  
BOX No. 96  
(TOW)

DISCLOSED  
BOX No. 96 Top

Has a survey been made of the ship? If so, is the Report sent now, or when will it be sent?

Is Certificate required? If so, to be sent to