

Lloyd's Register of Shipping,  
General Menacho 9,  
Cadiz, 15th. April 1929.

E. The Secretary,  
London.



Dear Sir,

I beg to state in reply to your letter of the 9th. inst. in reference to my Electric Light Report No. 1186 on the steamer "TORRES GARCIA" that I was not correct in stating that there are single pole fuses on the out going circuits, at the main switchboard. The statement should read "To each outgoing circuit, single pole switches and fuse on each pole!"

I am, Dear Sir,  
Yours faithfully,

Thomas Miller



EXC 199A

© 2020

Lloyd's Register  
Foundation

W1231-0038-1



Referred to the Chief Engineer Surveyor.

20 APR 1929

B.H.  
23/4/29

*Handwritten signature*

*Handwritten text*

*Faint, mostly illegible handwritten text, possibly a letter or report.*



© 2020  
Lloyd's Register  
Foundation