

Torres Garcia.

Cadiz 1186.

It is submitted the Surveyor be requested to state whether he is correct in ~~reporting~~ that the outgoing circuits at the main switchboard have single pole fuses, instead of double pole fuses as required by Sec 3. Par 3. 6(ii) of the Rules for Electric fittings.

W1251-0038.3



© 2020

8/4/27

Lloyd's Register  
Foundation