

TORRES GARCIA.

CADIZ 1186.

It is submitted that the Cadiz Surveyors be  
requested to state whether the H.P. cylinder  
ten inches or ten and a half inches  
diameter & to confirm the diameters  
of the crank shaft & the thrust shaft  
& collar.

lcl<sup>hr</sup>  
20/3/29

J.D.A. 20/3/29

T. J. A. T. (see J. Coasignara

Coasignara

41251-0045

24000

1 D<sup>c</sup>

Lloyd's Register  
Foundation