

W1252-0227

12.27

to Chief Surveyors _____

Received from Chief Surveyors _____

19. 5-31

SEL'S NAME _____ Steel Sc. Sr. "TAIUN MARU" N° 10 Report _____ Lon. _____ No. 96302a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

ure of Survey _____ When due _____

The 2nd S.S. No.1 became due 2.31.

The Kobe Surveyors now forward translation of a letter from the Owners stating it has been decided to withdraw this vessels class from the Register Book.

It is submitted the class of the vessel be withdrawn from the Register Book, and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...



© 2020

Lloyd's Register
Foundation

18.5.31.