

14 OCT 1932

Received from Chief Ship Surveyor

by Chief Ship Surveyor

Rpt. Cco. No. 548

EL'S NAME Steel S.S. "VINCAS"

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

of Survey


The class is subject to indented plating being dealt with at the Owners' convenience, 15 fathoms of chain cable being supplied and the weather decks, ventilators, hatch coamings, covers and supports being further examined and dealt with as found necessary on arrival in Australia via Curacao.

The Curacao Surveyors now report the vessel examined afloat on account of leakage of gasoline from the cargo tanks into store spaces, tunnel and cofferdams.

Temporary repairs have been effected and the Surveyors recommend the main cargo tanks be further examined and permanent repairs effected at the completion of the present voyage.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended and as above.

As now, subject etc.



© 2020

Lloyd's Register  
Foundation

W1254-0070