

COPY.

DIONI
AGXIK
TSUVO
EXKUF

- Arrived
- Ghent
- class has been expunged with a Red Line on account of non compliance with the Rules
- Owners desire vessel to be reclassified
- to entitle vessel to reinstatement of class
- all requirements of 3rd S.S. No.1 remain to be completed with except

OCEKO
OLJIM
PIBYG

ROOGY

- examination of fore and after peak tanks

ROFMI

- examination of chain locker

ROFOS

- examination of decks

ROFYV

- examination of tween decks

ROFDE

- examination of tween deck bunkers

ROSGU

- examination of windlass

SAZME

- Stop

SYFAB

- Wasted

NEGEV

- tank top plating

SOVZE

- under

ALPFU

- boilers

ACPUN

- also

AKYZE

- shifting beams

ADIMT

- and

JUXWI

- fore and afters

MEKEH

- of

SOLVY

- tween deck

ETHFE

- cargo

KONVA

- hatchways

OSOGD

- require to be repaired

SAZME

- Stop

RUKYG

- To complete machinery survey following remains to be done

RYLIJ

- examination of sea cocks and fastenings

NECKY

- indented shell plate

NAVVO

- plate No.-- in G strake

UHPEH

- 3

NELEB

- port side

OSGYP

- requires to be dealt with

KEWHA

- give case immediate attention



© 2020

Lloyd's Register
Foundation

W1256-0266