

Now named Hercules

F.E.

Received by Chief Ship Surveyor 26.10.05

Received from Chief Ship Surveyor

VESSEL'S NAME *Ste. Steam Trawler "Marshall Oyama"* Rpt. *Kull* No. *17282*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/02.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>1 5/16" in lieu of 2 1/2"</i>	<i>Not required</i>
Spar Sheerstrake . .	<i>"</i>	<i>"</i>
Description of Framing:— <i>Ordinary, increased to compensate for omission of reverse frames, and spaced 1" closer than required.</i>		

*The 3rd anchor is 5 lb. less in weight than required by Table 22, but the 1st & 2nd (stockless) anchors are 52 lb. and 122 lb. respectively in excess.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ 100 A 1 ("Steel") Steam Trawler* as recommended.

*+ 100 A 1 ("Steel") Steam Trawler**18R.**BK 8" 40H Ann. Lloyd's & CP Q 63' F22'**C.H.J.*  
*26/10/05*Lloyd's Register  
Foundation

W1256-0365