

15, ~~15/17~~

	<u>Date of Build</u>	<u>Gross Tons</u>	<u>Number in R.B.</u>	<u>Class, and surveys due, if any.</u>
r "GOUTHAMI"	1927	147	01244	⊗A- Dredger For Harbour Service. ⊗NB.12,27
"KERALA"	1925	78	11407	⊗A1 For Towing Services ⊗LMC.8,29 Boiler Survey due 11,31 Screwshaft Survey due 8,32
er "LORD WILLINGDON"	1926	864	12152	⊗A1 Dredger ⊗LMC.5,30 Boiler Survey due 4,32 Screwshaft Survey due 5,33

Owners: The Madras Government.

Correspondence has taken place with the Owners and the Society's Surveyors at Calcutta with a view to arrangements being made for carrying out the Society's Surveys on these vessels, which are in service in districts not reasonably accessible by the Society's Surveyors.

In reply to enquiry, the Owners now write that it has been decided, in the circumstances, to discontinue the arrangement under which these three vessels are periodically surveyed by the Society's Surveyors.

It may be mentioned that the vessels are chiefly engaged in work in the new Harbour of Cochin.

The Classing Committee had the cases before them on Friday, 20th instant, when in the circumstances they decided to give instructions for the character of each vessel to be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

26th October, 1933.



© 2020

Lloyd's Register
Foundation

10mg.33.—Transfer Ink.
not to write on or below the space for Committee's

Surv
Spec