

Advised
Frumby

S. 217

of HULL,

3rd September 1920

ARCHIBALD MC GLASHAY,

the Managers representative, survey the S.S. "FRANZISKA" 5129 tons gross of London No. 58335 in the Register Book, on the 30th August 1920 and subsequent dates as she lay afloat in the Alexandra Dock, for the purpose of ascertaining the general condition of the vessel.

The holds, tween decks, peaks, engine and boiler space and tank top under the boilers, bridge and tween deck bunkers and part of lower bunkers examined.

Limber boards lifted in holds and bilges examined.

Decks, engine and boiler casings, hatchways, hatch beams and hatches, masts and rigging -from deck- ventilators, windlass, steering gear and general equipment examined; 5 anchors aboard.

The vessel was not placed in dry dock, and cables not ranged and double bottom tanks not opened up for survey.

The frames, reverse frames, beams, bulkheads, stringers and decks examined and found in order.

The indented **tween deck** plating mentioned in previous reports was examined, and found to continue efficient.

© 2020



Lloyd's Register
Foundation

W1258-0147 1/2

Vertical text on the right edge of the page, including numbers and partial words: 6 1/2, 3, 4 1/2, 3 1/2 x, 35, 3 1/2 x 3, Steel, 66, 4 1/2 x 4, 35, 3 1/2 x 3.

judging from my inspection of the parts of the vessel which have
 now been examined and after reading the reports of the Surveyors
 on the surveys held at Leith on 8th. May 1919 and at Grimsby
 8th. November 1919, I am of opinion that the vessel appears to
 be in a fit condition to run for a period of six months from this
 date of survey.

A. M. Glashan.

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.



© 2020

Lloyd's Register
 Foundation

W1258-04712