

In damage cases where the Surveyor has not made a special damage

declined: *No damage*

TELEPHONE NO CENTRAL 4425 (2 LINES)

ices for this pur

TELEGRAMS, "REGISTER, NEWCASTLE"



Lloyd's Register of Shipping.

Collingwood Buildings, Newcastle-on-Tyne.

LLOYD'S REGISTER
LONDON.

REC'D 12 JAN 1921

ANSD

11th Jan 1921.

Reference

Dear Sir

S/S FRANZISKA

Replying to your telegram of today respecting the above steamer, I beg to say that the Special Survey with a view to classification on this steamer is now complete with the exception of the

following items:-

1. Stiffening of double bottom in way of wide spaced pillars.
2. Additional stiffeners to bulkheads in way of deck girder brackets.
3. Additional straps on deck girders
4. Additional connections to tunnel stiffeners
5. Wood Hatch covers to put in order
6. Retanking of tanks after repairs.

The foregoing work is all in hand & is expected to be finished in about one week

I beg to remain Dear Sir
Yours faithfully
J. A. Roberts

The Secretary
London

W1258-0156

Lloyd's Register
Foundation

W1258-0157

Referred to the Chief Ship Surveyor.

78 Mc.

Also for Mr. S. A. Hill to make.
Referred to Mr. Mayo.



© 2020

Lloyd's Register
Foundation