

LLOYD'S REGISTER OF SHIPPING

LLOYD'S REGISTER,
LONDON.

37 FURNESS WITHY BUILDING

RECEIVED MAR 1921

HALIFAX, N. S.

ANSO

February 23rd, 1921.

The Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street,

London, E.C.,

England.


Dear Sir:

On checking over the bower anchors for the S.S. "CANADIAN EXPLORER" (the Halifax Shipyards' Hull No. 2), it was found the collective weight was not sufficient, and on looking over the weights of the anchors for the S.S. "CANADIAN MARINER" it was found that the collective weight of these was more than sufficient. It was surmised that one of these anchors had been placed on the wrong vessel. As the steamer "CANADIAN MARINER" had returned from her maiden voyage the anchor (certificate No. 60) was changed for the anchor with certificate No. 59, thus giving the collective weight to both vessels. Enclosed please find particulars of the anchor, certificate No. 59, replacing anchor with certificate No. 60, which is being used for the S.S. "CANADIAN EXPLORER". The certificates for these have been altered accordingly.

I am, Dear Sir,

Yours faithfully,

J. Moon.



Lloyd's Register of Shipping

W12J8-0247

Angles on upper edge
Spacing
Tie Plates

BEANS, Forecastle Deck

Referred to the Chief Ship Surveyor.

18 MAR 1921

Also for Mr. S. A. Hill to notes

C. S. L.

[Handwritten initials]

И. И. ХАЛДИАН

31 БУКВЕНЪ МАЛУХЪ БОИДИЦА

ЛЛОЙДЪС РЕГИСТЕРЪ ОФ ШИППИНГ

ТЕЛЕФОНО: 206 КАИТЕ № 30



© 2020 Lloyd's Register Foundation