

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

11 FEB 1941

L'S NAME

"SOPHIE MARIE"

Rpt.

Krh

No.

762

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The KARACHI Surveyor reports this vessel placed in dry dock, bottom coated, A 2nd S.S. No. 3 due 10.39 held (vessel 17 years old) and minor wear and tear repairs effected.

60 fathoms of chain cable have been renewed but as the certificates were not to hand particulars will be forwarded when received.

It is submitted the vessel is worthy to remain as classed with record of survey 12.40 and notation of S.S. No. 3-12.40.

100A1

12.40 Krh

S.S. Krh No. 3-12.40.

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.

✓


asg  
7.2.41

Insert in S.R.L: (Certificate for 60 fms renewed cable to supply), in italics.

static note J.M.

X

It is concluded the examination and testing of the double bottom tank, examination of plating in way of sidelights, decks, anchors, chain locker, W.T. doors and ventilators, not specifically mentioned in the body of the report, have been dealt with for the Special Survey.



© 2020

Lloyd's Register  
Foundation

W126-0068