

"Pioneer"

W1263-0177

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

St. Helena

Rpt.

Stam

No.

13507

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

80.99

Depth "d"

16' 10"

Framing: Table No.

Description

Longitudinal

Longitudinal No.

3181

framing.

Proportions

Length

Depth

13.43

Upper Deck Sheerstrake together with other scantlings
as approved for vessel's build on the Longitudinal
system of framing.

This vessel appears to have been built in accordance with the
Rules and the approved plans, and it is submitted she is eligible to
be classed \pm 100 A-1. (Std) Carrying petroleum in bulk
as recommended.

\pm 100 A-1. (Std) Carrying petroleum in bulk

2 D² (Std) Web frames, longitudinal framing

NB. Bul DB n 6 + B 74 221' DT f 81' 480' FPT 169' APT 661'
FK. 13BH, 10BH to upper deck, 3BH to 2nd deck. Can Lloyd's 2760
P115 B22' F37'

E. L. R. B. 11
2/7/13