

116 MAR 1934

T.S.S. "TERESA ODERO"

The Genoa Surveyors report this vessel examined afloat, damage repairs effected, and the S.S.No.2, due January 1935, partly complied with as follows :-

Examination of fore and after peak tanks, forward hold and tween decks, auxiliary pump room forward, and centre portion between the side expansion trunks forward and aft.

Double bottom tank under forward hold tested under water pressure to Rule head and found tight.

Cargo tanks Nos. 2, 4 & 6 port and starboard tested by being filled with water to the height of the top of the upper deck oil-tight hatchways and found tight with the exception of a few leaks from the end bulkheads and from a few shell rivets through the ship's side stated attributable to damage.

Cargo tanks Nos. 1, 3, 5 & 7 were partially cleaned for the purposes of the tests on the adjacent tanks.

Masts and rigging examined.

A letter has been received from the Genoa Surveyors enclosing copies of letters from the Owners stating that for reasons of economy they have decided to dispense with the Society's classification. Mr. Ormiston states that he has been in touch with the Owners and that the matter has been reconsidered by them, but they could not see their way to depart from their decision.

The case is submitted for the consideration of the Committee.

16.3.34



© 2020

Lloyd's Register
Foundation

W1265-0231