

12-5-26  
Firegrate in each Boiler Oil fired No. and Description of safety valves to each boiler 2 spring loaded

COPY FOR LONDON OFFICE  
LLOYD'S REGISTER AND REGISTRO ITALIANO.  
FEES FOR DUAL CLASSIFICATION SURVEYS.

OF GENOA Date 4th FEBRUARY? 19 27  
e of Ship "TERESA ODERO"  
ber of Report

1 Lloyd's Register fee	...	...	S.S. During Construction	11800.00
1 Registro Italiano fee	...	...	...	Lit 7602.50
1 fees	...	...	...	Lit 19402.50
COMBINED FEE, i.e., 5/6 (LR + RI)	...	...	...	Lit 16168.50
per cent of 5/6 (LR + RI) to be credited to Registro Italiano	...	...	...	Lit 8407.50
per cent of 5/6 (LR + RI) to be credited to Lloyd's Register	...	...	...	Lit 7760.90

First Entry  
Lighting Expenses charged (to be credited to Lloyd's Register) ... Lit



© 2020

Lloyd's Register  
Foundation  
W1265-0252

combustion chamber tops: Material S.M. Steel Tensile strength 28/22 tons Working pressure