

# REPORT of SURVEY for REPAIRS, &c.

DISCLOSED  
BOX No. 13

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at... Date, First Survey... Last Survey 19... (No. of Visits)

05930  
12 JULY 1935

TONNAGE: Built at Selby By whom Lochane & Sons Ltd When 1914 5  
GROSS 283 Owners Ltd Baskomb  
UNDER DK 268 Managers  
NET 120

**RETAIN**

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
WB=CellDBorDBa feet; uE&B feet; f feet  
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 19271 Port Gms

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER	Year	Month
+100A1		10.31
Sm Hawker		8.31
H.35		11.35

SS Gms No 3-6.24  
SS Gms No 1-31

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? - If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

### PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
„ „ in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood, Vessels	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	„ length mean diam. (on board)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Treenails ditto	„ Rule length size
Transverses	Have Watertight Doors now been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Floors	Have Watertight Doors now been examined and found efficient?	Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	

### General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— to remain as now classed in the Register Book without fresh record of Survey, "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£
Special Damage or Repair Fee (if any) (per Sec. 20)	£
Travelling Expenses (if chargeable)	£
Second Surveyor's Fee (if any)	£

Fees applied for,	19
Received by me,	19

Surveyor to Lloyd's Register of Shipping

Committee's Minute  
Character Assigned  
write down L.O. 25/7  
19 JUL 1935  
Withdrew Class  
R/B

General Committee  
Thursday, 25th July, 1935

Decision of Classing  
Committee confirmed

Lloyd's Register  
Foundation

Is Certificate required? If so, to be sent to

W1269-0060