


of "Barle."

Hull Rpt 27544.

It is submitted the Hull Surveyors should be informed that it is concluded a set of spare coupling bolts has been placed on board but as no mention of this is made in the report they should state whether this is so.

JWD.

L 5/6/14



4/6/14 © 2020

Lloyd's Register
Foundation