

REGISTER.  
DON.

Time of Receipt

L-10

JAN 12 1916

# TELEGRAM.

13/1/16

N.B.—This Form must accompany any inquiry respecting this Telegram.

## POST OFFICE TELEGRAPHS.

If the Receiver of an Inland Telegram doubts its accuracy, he may have it repeated on payment of half the cost of transmission, any fraction of 1d. less than 1d. being reckoned as 1d.; and if it be found that there was any error, the repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams. See Instructions.

Office Stamp.

THREADNEEDLE  
STREET.

Charges } s. d.  
to pay }

JAN 12 1916

Handed }  
in at 8/27 AM.

Received }  
here at 8/37 M.

Committee

LONDON.

6114 Converted Oil Tank  
Equipment 2 1/4 Inch Cable  
anchors presume this acceptable  
view of reduced lengths  
Erections Earles



© 2020

Lloyd's Register  
W1269-0128  
Foundation



Referred to the Chief Ship Surveyors

CSA

JAN 12 1916



© 2020

Lloyd's Register  
Foundation

Register, I

AMING.

of L Bars

ple Bottoms

om centre to

length to Col

E, Angles...

le Bottoms a

ginder .....

d thickness

ie for 1 leng

ine and Boil

ie ends of ve

half breadth

ed at the Bil

ouble Bott

Solid floors

in Dbl. bottom

Angles, Top

Bottom

" to Fl

intermd. frmg

umber on each

tate if flanged

Angles (top an

" to Floor

depth (exclus

and thicken

Angle to Outs

" Floor

intermd. frmg

Outside Brack

PLATING,

ness of Middle

in Engine e

Remainder

Deck, Single

Plate, Tee B

Long Bridge

Fourth Deck

ngle Plate, Tee B

on upper edge