

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

21st September, 1934.

Dear Sir,

S.

With reference to the case of the steamer "SOUTHERN PRINCESS", Liverpool Reports No. 14340, I shall be glad if you will kindly ascertain from the Surveyors and let me know whether the boilers still work under forced draught, in which case the new figure for MHP should be 97.

With regard to the diagrammatic plan forwarded showing the arrangement of the various press boilers and their respective working pressures, the notation in the Register Book will be amended to read as follows:-

55 Press Boilers	-	80 lb
2 " "	-	50 lb
1 " "	-	45 lb

I would point out that in order to simplify the notation it has been the practice in this Office to regard a boiler with rotating drum and its accompanying separator as comprising one press boiler, and the Surveyor's figures have consequently been amended on these lines.

I am, Dear Sir,
Yours faithfully,

Clerk to the
Classification Committee.

The Secretary,
Lloyd's Register

© 2019

Lloyd's Register
Foundation

9400-121M