

It is submitted the Glasgow Surveyors should be requested to state with reference to the case of the S.S. "Visigoth" whether the timbers in the after hold were cemented and if so, to what extent the thickness of the cement at the bottom of the timber would raise above the level of the frame and its drainage tendency at any trim of the vessel, it being observed that the figured dimensions shown on the builder's sketch refer only to the intersection of the outer edge of margin plate with the shell plating

GB 29/5/06

Lt Ldo 29/5/06

J.M.



© 2021

Lloyd's Register  
Foundation

W1272-0198